

United States Of America  
Department of Transportation - Federal Aviation Administration

# Supplemental Type Certificate

*Number* SA02337AK

*This Certificate issued to* Aero Twin, Inc.  
2403 Merrill Field Drive  
Anchorage, AK 99501

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.*

*Original Product Type Certificate Number:* A00007SE

*Make:* QUEST

*Model:* Kodiak 100

*Description of Type Design Change:* Installation of up to eight (8) seats, Aero Twin, P/N DFS2T-L/R, in loading zones two through five in accordance with Master Data List Doc. No. DFS-KOD-MDL dated March 2, 2009, or later approved revision.

*Limitations and Conditions:*

- 1) Compatibility of this design change with other previously approved modifications must be determined by the installer.
- 2) If the certificate holder agrees to permit another person to use this certificate to alter the product, then the holder must give the other person written evidence of such permission.
- 3) FAA Approved Airplane Flight Manual Supplement (AFMS) original issue dated March 24, 2009, or later FAA approved revision is a required part of this STC.
- 4) Instructions for Continued Airworthiness, Aero Twin, Inc. document number DFS-KOD-ICA, Original Issue, dated December 25, 2008, or later FAA accepted revision is a required part of this modification.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* December 22, 2008

*Date reissued:*

*Date of issuance:* March 27, 2009

*Date amended:*



*By direction of the Administrator*

*Gregory J. Holt*  
(Signature)

Gregory J. Holt  
Manager, Anchorage Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.